

SF File Number

20.8

1263493 - R8 SDMS

facility id# 15-09527tank no. #1

## TANK CLOSURE FORM

(a separate form needs to be filled out for each tank closed)

## TANK OWNER'S NAME &amp; ADDRESS:

Burlington Northern Railroad  
9401 Indian Creek Parkway  
Overland Park, Kansas  
66201-9176

## FACILITY NAME AND

## LOCATION ADDRESS OF TANK:

Burlington Northern Tie Plant  
Somers, Montana

1. TANK AGE (YEARS): unk 2. TANK CAPACITY (GALLONS): 20,000
3. WHAT SUBSTANCE WAS LAST STORED IN THE TANK? Bunker Oil
4. WHEN WAS TANK LAST USED? (month/year) unknown
5. DATE OF CLOSURE? 12-12-90
6. TYPE OF CLOSURE:  
☒ Removed from Ground ☐ Filled with Inert Solid [Please describe inert solid (e.g. sand, concrete)]

7. TANK - CONDITION AND MATERIAL (Check any that apply and include a complete description of the affected area. This may include photographs or tank test results.)

## Condition:

☐ Pitted ☐ Perforated ☐ Cracked ☐ Rusty ☒ Good Condition

## Material of Construction:

☒ Steel ☐ Concrete ☐ Fiberglass Reinforced Plastic  
☐ Cathodically Protected ☐ Other, please specify

## COMMENTS:

Tank looked in good condition. There was NO evidence of Corrosion or Rusting.

8. PIPING - CONDITION AND MATERIAL (Check all that apply and include a complete description of the affected area. This may include photographs or piping test results.):

## Condition:

☒ Pitted ☐ Perforated ☐ Cracked ☐ Rusty ☐ Crushed  
☒ Good Condition

## Material of Construction:

☒ Bare Steel ☐ Galvanized Steel ☐ Fiberglass Reinforced Plastic  
☐ Cathodically Protected ☐ Other, please specify

## COMMENTS:

Piping was removed from tank  
Samples were taken every 50' there were two samples  
taken & composited into one sample.  
There was 50' of piping all together



418345

9. NAME, ADDRESS AND PHONE NUMBER OF CLOSURE CONTRACTOR:

Olympus Environmental  
1660 B. St  
Helena MT. 59601

10. NAME(S), ADDRESS(ES) AND PHONE NUMBER(S) OF LOCAL, COUNTY OR STATE OFFICIALS WHO WITNESSED CLOSURE (Include statements if available.):

11. COMPLETE DESCRIPTION OF CLOSURE PROCEDURE (including disposition of tank and contaminated soil):

The tank was excavated from all sides after bunker was pumped out. Then it was removed from the excavation. It was entered + cleaned. Then it was cut + stockpiled on site. Soil underneath the tank was not visually contaminated + did NOT have any odor to it.

12. EXPLANATION OF SITE ASSESSMENT (Check any which apply and include a description of what the soil under the tank looked like and test results from soil borings, soil/water/vapor samples and estimated depth to groundwater):

\_\_\_ smell of fuel      \_\_\_ discoloration      \_\_\_ free product  
\_\_\_ sheen on groundwater      ☒ no evidence of leak      \_\_\_ samples attached

COMMENTS:

Soil samples were taken from each end of tank  
Tip Readings were conducted Results: #1 5 #2 7  
Samples were also taken from PIPING Tip Readings 3  
Lab analysis are attached

Owner Signature Melvin L. Burke Title Manager Environmental Dept Date 1-18-91

Contractor Signature John Birch Title Field Sup. Date 12-12-90

Local, County or State official who witnessed closure:

Signature \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

Return completed form within 30 days of closure to:

UST Program/Solid & Hazardous Waste Bureau  
Department of Health & Environmental Sciences  
Cogswell Building, Room 8201  
Helena, MT 59620

close.frm  
rev. 01/89

Please retain a copy for your files.

# CHAIN OF CUSTODY RECORD

Client/Project Name <b>3088 BN</b>				Project Location <b>Somers MT.</b>				ANALYSES							
Work Order No. <b>3088</b>				Field Logbook No.											
Sampler: (Signature) <i>[Signature]</i>				Chain of Custody Tape No.											

  

Sample No./ Identification	Date	Time	Lab Sample Number	Type of Sample											
3088-1	12-11	15:45		Soil	✓										
3088-2	12-11	15:50			✓										
3088-3	12-12	14:00			✓										

  

Relinquished by: (Signature) <i>[Signature]</i>		Date <b>12-17</b>	Time <b>0800</b>	Received by: (Signature) <i>[Signature]</i>		Date <b>12-17</b>	Time <b>1505</b>
Relinquished by: (Signature)		Date	Time	Received by: (Signature)		Date	Time
Relinquished by: (Signature)		Date	Time	Received by: (Signature)		Date	Time

  

Comments: <b>Send Copies + Results to Olympus Environmental</b>	ANALYTICAL LABORATORY
--	-----------------------

**ENERGY LABORATORIES, INC.**

P.O. BOX 30916 • 1107 SOUTH BROADWAY • BILLINGS, MT 59107-0916 • PHONE (406) 252-6325  
FAX (406) 252-6069 • 1-800-873-5227

**LABORATORY REPORT**

**TO:** Olympus Environmental  
**ADDRESS:** 1660 B Street  
Helena, MT 59601

**LAB. NO:** 90-34685 -87  
**DATE:** 01/09/91 rs

**SOIL ANALYSIS**

Somers, MT  
Submitted 12/20/90

<u>Lab No.</u>	<u>Identification</u>	Total Petroleum Hydrocarbons as Oil <u>by GC, <math>\mu\text{g/g}</math> (ppm)</u>
90-34685	3088-1, Sampled 12/11/90 @ 1545	< 10
90-34686	3088-2, Sampled 12/11/90 @ 1550	< 10
90-34687	3088-3, Sampled 12/12/90 @ 1400	< 10

Note: Analysis by EPA Method 8015.